Table 1: Sample Collection Information and Validated Analytical Data Summary Puerto Rico Olefins Asbestos Site Peñuelas, Puerto Rico January 2 and 3, 2014

| | | | | | Sample | | | | | | | Asbestos | Sensitivity * | Concentration |
|---------------|-----------------|--------------|-----------------|-------------|--------|--------|------------|-------------------|----------------|--------------|---------------|------------|------------------------|------------------------|
| Sample No. | Sample Area | Area Surface | Sample Location | Sample Date | Time | Matrix | Collection | Collected by | Analysis | Sample Type | Asbestos Type | Structures | (str/cm ²) | (str/cm ²) |
| P0029-WP01-01 | Top of Light | Metal | Porch | 1/2/2014 | 12:09 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 23 | 4,850 | 112,000 |
| P0030-WP01-01 | Lid Under House | Metal | Garage | 1/2/2014 | 12:29 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | None Detected | < 2.99 | 970 | <2,990 |
| P0031-WP01-01 | Top of Wall | Concrete | Top of Wall | 1/2/2014 | 12:43 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 28 | 4,850 | 136,000 |
| P0032-WP01-01 | Pan | Metal | Laundry Storage | 1/2/2014 | 12:57 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 5 | 970 | 4,850 |
| P0033-WP01-01 | Washing Machine | Metal | Outside Garage | 1/2/2014 | 13:38 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 5 | 970 | 4,850 |
| P0034-WP01-01 | Porch Ledge | Concrete | Balcony Wall | 1/2/2014 | 13:50 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 11 | 485 | 5,340 |
| P0035-WP01-01 | Traffic Barrier | Metal | Road 384 km 3.2 | 1/3/2014 | 09:10 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 24 | 4,850 | 116,000 |
| P0036-WP01-01 | Seat | Concrete | Bus Stop | 1/3/2014 | 09:21 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 33 | 4,850 | 160,000 |
| P0037-WP01-01 | Pressure Tank | Metal | Pool Area | 1/3/2014 | 10:24 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 27 | 1,940 | 52,400 |
| P0038-WP01-01 | Wall Vent | Concrete | Garage | 1/3/2014 | 10:51 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | 5 | 4,850 | 24,300 |
| P0039-WP01-01 | Traffic Barrier | Metal | Jail Road | 1/3/2014 | 11:21 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | None Detected | < 2.99 | 1,940 | <5,800 |
| P0040-WP01-01 | Traffic Barrier | Metal | Jail Road | 1/3/2014 | 11:33 | Wipe | Grab | Emilio Betancourt | Asbestos - TEM | Field Sample | Chrysotile | < 2.99 | 1,940 | <5,800 |
| FB-010213 | NA | NA | NA | 1/2/2014 | 12:05 | Wipe | Grab | Carlos Huertas | Asbestos - TEM | Field Blank | None Detected | <2.99 | NA | NA |

^{*} Due to excessive particulate the analytical sensitivity of 260 str/cm² as required by the method was not reached.

NA - Not Applicable

TEM - Transmission Electron Microscopy

str/cm² - Structures per Square Centimeter